

Play Equipment Inspection Report

Name S.Coates
Date 22/04/2026

		Item Description/Name	Satisfactory	Not Satisfactory	Hazard	Risk (L/M/H)	Recommended Action	
Covingham Park	Skate Park	General Surfacing	√					
		Seats/Benches	√					
		Bin	√					
		Signage	√					
		Quarter Pipe	√					
		Flat Ramp	√					
		Wave Ramp	√					
		Fun Box with steps	√					
		Full Pyramid	√					
		Straight Grind Rail (1)	√					
	Straight Grind Rail (2)	√						
	Toddler Play Area	General Surfacing	√				L	Slight damage to surface next to rocker
		Seats/Benches	√					
		Bin	√					
		Gates & Entrance	√					
		Perimeter Fencing	√					
		Signage	√					
		The Cloud	√					
		Rock 'n' Bowl	√					
		Rocker Yellow	√					
	Double Swing	√						
	Junior Play Area	General Surfacing	√				L	Small damage to surface
		Seats/Benches	√					
		Gates & Entrance	√					
		Perimeter Fencing	√					
		Signage	√					
		Gaheris' Castle Multiplay unit	√					
		Flymobile Roundabout	√					
		Buddy Board	√					
		Double Swing	√					
	MUGA	General Surface	√					
		Fences	√					
		Signage	√					
		MUGA walls	√					
	Adult Exercise Equipment	General Surface (matting/grass)	√				L	To be levelled in the spring
		Signage	√					
Steps		√				L	to be painted	
Cross Rider		x						
Rower		√						
Cycle		√						
Air Walker		√						
Skier		√						
Body Twist		√						
Rider		√						
Chest Press		√						
Smittenbrook Park	Basket Ball Court	General Surface	√					
		Signage	√					
		Basket Ball Post (1)	√					
		Basket Ball Post (2)	√					