

Play Equipment Inspection Report

Name A.Hughes
Date 26/08/2026

		Item Description/Name	Satisfactory	Not Satisfactory	Hazard	Risk (L/M/H)	Recommended Action
Covingham Park	Skate Park	General Surfacing		√	Old post protruding surface	H	Referred to SBC
		Seats/Benches	√				
		Bin	√				
		Signage	√				
		Quarter Pipe	√				
		Flat Ramp	√				
		Wave Ramp	√				
		Fun Box with steps	√				
		Full Pyramid	√				
		Straight Grind Rail (1)	√				
		Straight Grind Rail (2)	√				
	Toddler Play Area	General Surfacing	√			L	2 x Slight damage to surface
		Seats/Benches	√				
		Bin	√				
		Gates & Entrance		√	Dry weather has caused subsidence	L	
		Perimeter Fencing	√				
		Signage	√				
		The Cloud	√				
		Rock 'n' Bowl	√				
		Rocker Yellow	√				
		Double Swing	√				
	Junior Play Area	General Surfacing	√			L	Small damage to surface
		Seats/Benches	√				
		Gates & Entrance	√				
		Perimeter Fencing	√				
		Signage	√				
		Gaheris' Castle Multiplay unit	√				
		Flymobile Roundabout	√				
		Buddy Board	√				
	MUGA	Double Swing	√				
		General Surface	√				
		Fences	√				
		Signage	√				
		MUGA walls	√				
	Adult Exercise Equipment	General Surface (matting/grass)	√				
		Signage	√				
		Steps		√		L	to be painted
		Cross Rider	√				
		Rower	√				
		Cycle	√				
		Air Walker	√				
		Skier	√				
		Body Twist	√				
		Rider	√				
		Chest Press	√				
Smittenbrook Park	Basket Ball Court	General Surface	√				
		Signage	√				
		Basket Ball Post (1)	√				
		Basket Ball Post (2)	√				